



INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com

- Site Report -

Date: January 15 2009

IRD Sales Order: 11013

To: Greg Felsing

From: Bryan Knight

Project Name/Location: Chloride AZ / SR93 N mp 51

Service Date(s): January 15 2009

Job Description: Performed Annual System Health Check.

Work Completed: Measured and Recorded the Inductance, Resistance, and Voltage readings of the in-road sensors (Bending Plate and Loops). Measured Solar Panel Output and MODEM supply voltage. No discrepancies noted. System is fully functional.

Work Remaining: None

Schedule Include Estimate to Complete (on-track, ahead, behind): N/A

Parts Used: None

Pre-mature Equipment Failure: None Noted

Mileage / Travel Time: Total Travel: 2 hrs. Total Onsite: 1 hr.

Safety Concerns:

Issues Related to Sub-Contractors:

Other Notes:

Action Items:

| Item | Action Required | Ownership |
|-------------|------------------------|------------------|
| 1. | | |
| 2. | | |
| 3. | | |
| 4. | | |